## **Fire Safety Management Compliance** London Borough of Redbridge Broomhill Road 19-19c Location: 19/02/2018 **Date Checklist Completed** FRA Issue Date: 06/11/2015 **Compartmentation Issue Date:** N/A 02/09/2017 **Internal Review Date:** 14/08/2017 **Management Review Date: Communal Areas** Date Comments A fire risk assessment has been issued for the premises Yes Priority 2 - Every three The fire risk assessment is due for review years FRA Next Due: 05/11/2018 Work identified in action plan Works require inspection Work identified in compatmentation survey Works require inspection Emergency Exit Plans are located on each floor of the premise directing persons N/A Provision has been made to evacuate persons identified as being especially at N/A risk? No For communal areas emergency escape lighting is provided and tested? Door schedule Total number of doors 75% Number of flat entrance doors which are considered nominal / fire door Number of flat entrance doors which are non - fire doors Communal fire doors have been inspected to ensure they are self-closing, have No fire intumescent seals, are usable, clear of obstruction, and they lead to a place Visual inspection of the condition of the wall coverings or decoration are in a Yes reasonable state of repair? Visual inspection of the condition of the floor surface / covering is in a reasonable Yes The date of the last fixed wire inspection for communal areas? These should be reinspected every 5 year or following change of tenancy. Measures are in place to keep external areas of the premises clear for access / Yes egress and free of combustible materials? The premise Dry Riser was inspected? N/A **Residential Area** Date **Comments** Provision has been made to evacuate persons identified as being especially at risk N/A Percentage of properties with fire alarm / smoke detectors, if known? Yes #DIV/0! No Percentage of properties with Carbon Monoxide detectors, if known? Yes #DIV/0! No