Fire Safety Management Compliance London Borough of Redbridge Location: 1-40 Cherry Court, IG6 2BL 19/02/2018 **Date Checklist Completed** FRA Issue Date: 25/02/2015 Compartmentation Issue Date: N/A **Internal Review Date:** 13/06/2017 21/10/2016 **Management Review Date: Communal Areas** Date Comments A fire risk assessment has been issued for the premises Yes Priority 2 - Every three The fire risk assessment is due for review FRA Next Due: 24/02/2018 Work identified in action plan Works require inspection Work identified in compatmentation survey Emergency Exit Plans are located on each floor of the premise directing persons Yes to safety? Provision has been made to evacuate persons identified as being especially at N/A For communal areas emergency escape lighting is provided and tested? Yes Door schedule 40 Total number of doors 78% Number of flat entrance doors which are considered nominal / fire door 9 31 Number of flat entrance doors which are non - fire doors Communal fire doors have been inspected to ensure they are self-closing, have N/A fire intumescent seals, are usable, clear of obstruction, and they lead to a place of final safety? Visual inspection of the condition of the wall coverings or decoration are in a Yes reasonable state of repair? Visual inspection of the condition of the floor surface / covering is in a reasonable Yes condition? The date of the last fixed wire inspection for communal areas? These should be reinspected every 5 year or following change of tenancy. Measures are in place to keep external areas of the premises clear for access / Yes egress and free of combustible materials? The premise Dry Riser was inspected? N/A **Residential Area** Date **Comments** Provision has been made to evacuate persons identified as being especially at risk Percentage of properties with fire alarm / smoke detectors, if known? Yes #DIV/0! No Percentage of properties with Carbon Monoxide detectors, if known? Yes #DIV/0! No