Fire Safety Management Compliance London Borough of Redbridge Location: Foremark Close (24-32), IG6 3EN 19/02/2018 **Date Checklist Completed** FRA Issue Date: 06/02/2015 Compartmentation Issue Date: N/A **Internal Review Date:** 06/03/2017 06/03/2017 **Management Review Date: Communal Areas** Date Comments A fire risk assessment has been issued for the premises Yes Priority 2 - Every three The fire risk assessment is due for review years FRA Next Due: 05/02/2018 Work identified in action plan Works require inspection Work identified in compatmentation survey Emergency Exit Plans are located on each floor of the premise directing persons N/A to safety? Provision has been made to evacuate persons identified as being especially at No No For communal areas emergency escape lighting is provided and tested? Door schedule Total number of doors 9 0% Number of flat entrance doors which are considered nominal / fire door Number of flat entrance doors which are non - fire doors Communal fire doors have been inspected to ensure they are self-closing, have N/A fire intumescent seals, are usable, clear of obstruction, and they lead to a place of final safety? Visual inspection of the condition of the wall coverings or decoration are in a Yes reasonable state of repair? Visual inspection of the condition of the floor surface / covering is in a reasonable Yes condition? The date of the last fixed wire inspection for communal areas? These should be reinspected every 5 year or following change of tenancy. Measures are in place to keep external areas of the premises clear for access / Yes egress and free of combustible materials? The premise Dry Riser was inspected? N/A **Residential Area** Date **Comments** Provision has been made to evacuate persons identified as being especially at risk Percentage of properties with fire alarm / smoke detectors, if known? Yes #DIV/0! No Percentage of properties with Carbon Monoxide detectors, if known? Yes #DIV/0! No